

Forging a Square Punch and Drift

Text by Tal Harris

Drawings by Doug Wilson

Lesson #21. Unit: Forging a Square Punch and Drift

Intent: The student will learn to forge a square punch and square drift. Heat treating the punch will be covered in a future lesson. These tools will be used in a to produce a 3/8" square hole in a piece of 3/8" x 1" flat stock.

Tools: Basic tools, including tongs to hold the piece being forged.

Materials: For the punch- 3/4" square W-1 Tool Steel, six inches long. W-1 is a water hardening tool steel that is suitable for tools that come in contact with hot metal such as the subject application. W-1 is readily available in small quantities shippable by UPS. A tool properly made from this steel will last for many years.

For the drift- 3/8" square hot-rolled mild steel stock 2-3/4 inches long.

Forging a Punch

Step 1

Forging the end of the punch that will be used to produce a hole.


To forge the end of the tool that will be used to punch a hole (hereafter called the "working end" of the tool), heat the end of the punch material to an orange-yellow heat and forge a taper three inches long.

Note: Tool steels typically are not forged as hot as mild steel. The alloying elements found in tool steels lower the melting point, thus the forging range. Overheated tool steel will generally fracture when forged, sometimes falling apart like cornbread. Ideally, tools should be forged in as few heats as possible to minimize decarburization or "decarb" for short. Decarb is the loss of carbon at the surface of the material due to carbon migrating from the high-carbon tool to the lesser-carbon atmosphere. Carbon is the key alloying element in W-1 that allows it to be hardened. Loss of carbon lessens the degree or surface hardness the material can attain. A coal fire minimizes this affect as the coal provides a carbon-rich atmosphere.

To forge the three-inch taper start at the tip and forge back up the bar. Start forging the taper at the end of the bar, holding the end of the material being forged near the far edge of the anvil. This will allow the taper to be forged without hitting the face of the anvil with the hammer. To forge a taper that is centered, the material should be held at a 4-degree angle to the face of the anvil as represented in the drawing, with hammer blows being struck with the hammer face at an angle of 8 degrees to the hammer face. Forge to a square cross-section, rotating the bar 90 degrees back and forth between hammer blows. If the proper holding and hammer angle has been maintained, the taper

should be centered. Once the end of the bar has been reduced to 5/16" square, continue to forge up the bar three inches to complete the transition to the parent material. If more than one heat is required, be careful not to burn the material as the reduced section will heat quickly (you can tell you are burning the material because it will spark while in the fire). The taper should make a smooth transition from the parent material to the end of the piece without any twist. W-1 is a tough material. With experience this taper should be able to be forged in three to four heats.

Step 2



1. Holding the material at an angle to produce the desired taper

To forge the striking end of the punch, follow the same directions for the working end, but the taper should be short, 1 inch long, tapering from the parent material to 5/8" square. The angle of the taper will be almost identical to the working end of the tool. As this taper is short, it can be forged entirely over the face of the anvil and should be able to be forged in one or two heats. Occasional hammer blows directed at the end of the punch, as if striking it during actual use, will keep the end flat so no filing is necessary to achieve the properly shaped tool.

The purpose of this short taper is to delay the tendency of the striking end to "mushroom." It also helps to center the force of the blow during the hole-punching process.

Step 3

Once forged, it is best to anneal the tool to relieve forging stresses and soften it for any cold working operations such as filing. During forging, tool steels tend to get "uptight." Just as a person who gets uptight needs to relax before they "snap," the same is true for tool steel. One definition of annealing is "The heating of metal and then cooling it at a slow, consistent rate, thus reducing internal stress in the work piece and making it softer and easier to perform cold operations including filing."

CONTROLLED HAND FORGING


In this example, to anneal the tool it should be heated uniformly to an orange heat and then buried in lime or wood ashes to allow it to cool slowly. For a tool of this size, the quantity of lime or ashes required is about a gallon. The intent is to surround the tool completely so it is thoroughly insulated. It will take several hours to cool, so don't be impatient and search for the tool with your hand as a severe burn could be experienced. If properly annealed, the tool should cut easily with a sharp file. If not, repeating the annealing process may be necessary.

Note: Forge scale can greatly reduce the life of a file. An easy way to remove this scale is to soak the piece overnight in vinegar. Vinegar contains acetic acid and will dissolve the scale.

Step 4

Once cooled (and only if necessary) file the ends of the tool to remove any unevenness from the forging. The working end of the tool should be square with sharp corners so it cuts its way through the material being punched. Important! Remember to file from the body of the tool towards the end to avoid getting cut on sharp edges of the tool. A tool that is not sharp will result in a hole that has a reduced thickness around it due to the "drag" of the tool.


As W-1 is a tough steel, and mild steel heated properly to punch



2. "Drag" caused by a dull tool. Drag is the tendency to pull some of the surface of the steel down into the hole to be punched, rather than cutting cleanly.

and drift a hole is very soft, this tool may be used successfully in the as-forged condition, i.e., not fully heat treated.

Note: The square section of the punch has several advantages. Since the tool was forged without twist, the end of the tool that produces the hole is aligned with the body of the tool. This makes placing the tool to produce a hole of desired orientation much easier, whether the tool is hand-held or held with tongs.



3. Starting stock size and finished dimensions of the punch.

Also a tool forged from square stock will not roll off the anvil.

The tool described is intended to be used as a hand-held tool. As always, extreme caution should be exercised when using any hand-held tool. Remember that a misplaced blow places your hand between a hammer and a hot place. Often the material being punched will automatically lead us to whether a tool can be hand-held or should be held by some other means, such as tongs. Small-sized stock does not radiate as much heat as a larger piece and a punch can be held with a wet or Kevlar-gloved hand. For hole punching heavier sections the use of a handled tool is required. One will also find that the force required to punch a hole in larger sections will tend to bend the punch if it is too long. A shorter punch directs more force to the working end of the tool, making the work more efficient. The short tool uses less of an expensive material and eliminates the problem of bending when using a heavy blow. Complete and proper use of the punch and drift will be covered in a future lesson.

Targets:

- The tapered sections of the punch should be straight, centered and without twist.
- The faces of the taper should have no concavity or convexity.
- The long taper of the punch should have sharp corners as should the end of the punch that will produce a hole. This will allow the material to be sheared out cleanly when producing a hole.
- The taper on the striking end of the drift should be easily made in two heats. The opposite end should be able to be finished in three to four heats, the final heat being used to smooth and accurately center the taper.
- The length of the taper on the striking end of the punch is 1".
- The length of the taper of the working end is 3".
- The final length of the entire punch should be 7-3/8" and the working end of the tool 5/16" square.

Forging a Drift:

Step 1 - Forging the Working End of the Drift:

Following the same steps as when forging the punch, heat the end of the drift material to a yellow heat and forge a two-inch long taper using the face of the anvil, tapering from the parent stock size to 1/4" square, with the taper centered on the bar.

1-3/8 inches of 3/8" square material will be needed for this taper.

Note: The small end of the drift will need to be able to be placed in the hole produced by the punch. As before, if more than one heat is required, be careful not to burn the material as the reduced section will heat quickly. The taper should be even, centered and without twist. The long taper on this end of the drift, allows it to be easily driven into the hole being drifted. In actual use the end result will be a hole that has a nice bulge without the stock being reduced in thickness near the hole. Reduction in thickness near a punched hole is commonly referred to as "drag" and is affected by the taper of the end of the tool producing the effect. The shorter or more blunt the taper, the greater the drag. Alternatively, a longer and more gradual taper minimizes this effect.

Step 2 - Forging the Striking End of the Drift:

Follow the same directions for the working end. *Important!* The taper on the striking end must be longer than 3/8", the thickness of the material being drifted. Otherwise the drift cannot be driven through from one direction as it will get stuck in the hole being produced. A taper 1/2" long produced from 3/8" long of the starting stock will be correct for this tool.

As the drift is intended to be used only on hot material, it is not necessary that it be made from anything other than mild steel. If forged carefully, little or no filing will be necessary. Quenching mild steel from an orange heat will stiffen the drift and provide better service.


material, stand it on end (vertically) on the anvil, holding it from the side with a pair of tongs. Strike a few light blows on the end of the material to increase its cross-section. Usually when the material has moved sufficiently to cause the scale to fall off, it is upset enough to allow a bar to pass through the hole.

Targets:

- The tapered sections of the drift should be straight, centered and without twist.
- The faces of the taper should have no concavity or convexity.
- The long taper of the drift should have sharp corners but the end geometry is not critical as long as it extends through the 3/8" thick bar when inserted into the hole. The aim dimension for this end of the drift is 1/4" square.
- The taper on the striking end of the drift should be easily made in one heat. The opposite end should be able to be finished in two heats, the second heat being used to smooth and accurately center the taper.
- The final length of the drift should be 2-1/2 inches.

ChiliForge

1/4 page



3. Starting stock size and finished dimensions of the drift.

Note: The drift forged in this example will result in a hole that is slightly less than 3/8" square when the workpiece cooled. This is due to shrinkage that occurs between the time the hole is drifted and the piece cools. If a 3/8" square bar is to pass through the hole, then the drift material would need to be upset slightly prior to Step 1. To accomplish this, take a yellow heat on the starting